

CERTIFICATE OF COMPLIANCE

Certificate Number 20150622-R13976
Report Reference R13976-19910125
Issue Date 2015-JUNE-22

Issued to: SECURITRON MAGNALOCK CORP
10027 S 51ST ST
PHOENIX AZ 85044

**This is to certify that
representative samples of**

AUXILIARY LOCKS

Auxiliary Locks Series M82, M68, M62, M38, M34, M32, SAM, SAMSC, SAM2-12 and SAM2-24 with suffix letters C, DV, S, L, F or G, for installation on Listed firedoor frames and/or Classified swinging firedoors rated up to and including 1 hr. Series M38, M34, M32, M32B, M34RB, M62B, M82B, SAMB and SAM

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety:


Fire Tests of Door Assemblies - UL 10B.
Positive Pressure Fire Tests of Door Assemblies - UL 10C.
Standard Method for Fire Tests of Door Assemblies - CAN4 5104-M80.

Additional Information:

See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

