

II-M1500-9

FOR USE WITH M1500
MORTISE LOCKS WITH DEAD LATCH MONITORING (AM) MONITORING

AM - DEAD LATCH MONITORING

DEAD LATCH MONITORING IS A SPDT SWITCH MOUNTED INSIDE THE LOCKSET.
AM SWITCH MONITORS THE POSITION OF THE DEAD LATCH FUNCTION OF LOCKSET.
THE LOCKSET MUST BE IN THE CLOSED POSITION WITH THE AUXILIARY LATCH DEPRESSED
AND MAIN LATCH EXTENDED TO ACTIVATE SWITCH.

ELECTRICAL SPECIFICATIONS

SPDT MECHANICAL SWITCH	
VOLTAGE	CURRENT
125 VAC	3 AMP
30 VDC	2 AMP

NOTE: MAINLY USED AS A DRY CONTACT MONITORING SWITCH

